Сору

## PHOTOGRAPHIC INTELLIGENCE BRIEF CIA/RR-HTA

LOCATION:	Pavlodar Aluminum Co Pavlodar, USSR None 162	ombine	DATE: LAT.: LONG.:	B-91-57 1 October 1957 52 <sup>0</sup> 18' N 76 <sup>0</sup> 58'E
REFERENCE:				
ATMP:		lst Ed.,	Nov 1955	

REQUIREMENT RR/HTA/E/R39/57: Locate and describe the new aluminum combine reportedly under construction in the vicinity of Pavlodar, USSR.

## REMARKS:

25X1D

25X1A

The area within a 17-mile radius of Pavlodar has been scanned for a reported aluminum combine. There is no installation within this area that can be so identified.

On the northeast outskirts of Pavlodar a plant is under construction within a fenced area 4,700 by 3,100 feet. Foundations for four buildings are under way, and ditches for pipelines have been dug. However, the dimensions and shapes of the building foundations now present are not what would be expected for pot rooms or other components of an aluminun plant.

**Declass Review by NGA / DoD** 

AUTH: HR 70-2			11195	9
NEXT REVIEW DATE:				=
() DECLASSIFIED CLASS, CHANGED TO: NEXT REVIEW DATE:	TS	6	C 20/2	_
[] DEGLASSIFIED				
NO CHANGE IN CLASS.				
DOCUMENT NO				

Approved For Release 2004/12/01 : CIA-RDP78T04753A000100050007-1